

- Place weighing pan on balance; the conical peg centers the pan in the opening in the base of the weighing chamber.
- The two leveling screws should be adjusted so that the bubble is in the middle of the circle.

Whenever the location of the balance is changed, the balance should be leveled.

Operation

Short-form operating instructions

Short-form operating instructions can be found on a card that swings out from underneath the balance housing.

Switching the display on/off

- Briefly press the single control bar; all display segments light up for several seconds:

8.8.8.8.8.8.8.8.

- Afterwards, the display automatically sets itself to zero.
- Lightly lift the control bar; the display is switched off.

Calibration

Make absolutely sure:
The balance must be left connected to the power supply for at least 60 minutes before "calibrating".

- Press and hold the single control bar until -CAL- appears in the display, then release control bar. The display changes to CAL----, then to CAL100 (blinks).
- Move calibration lever all the way to the rear; the display changes to CAL----, followed by 100.000, then to CAL 0 (blinks).
- Move calibration lever all the way back towards the front of the balance; the display changes to ----, followed by zero.

Measuring cycle/measuring accuracy

By selecting a particular integration cycle, as well as a particular stability detection step, the balance can be configured according to your weighing location and needs.

Integration time:

Step 1: Used for very stable, vibration-free weighing table (short measuring cycle).

Step 2: Normal setting.

Step 3: Used for unfavorable ambient conditions (long measuring cycle).

- Press the control bar and hold it until -Int- appears in the display, then release the control bar.
- Immediately press the control bar briefly; the display will change to the next step.
- Stop at the step you wish to use and wait for the display to return to the weighing mode (zero).

Stability detector:

Step 1: Great sensitivity (long pause before data are released).

Step 2: Less sensitivity (short pause before data are released).

Normal setting.

The stability detector is switched off. Make sure that when this is the case, DeltaDisplay is also switched off (described in Paragraph entitled, "Weighing-in").

- Press the control bar and hold until -ASd- appears in the display, then release control bar.
- Immediately press control bar again briefly; the display changes to the next step.
- Stop at the step you wish to use and wait for the display returns to the weighing mode (zero).

Note: After selecting the integration time, you can go directly to the selection of the stability detector setting by holding the control bar down.

Taring

- Open the sliding glass door.
- Place a tare container on the weighing pan.
- Close the sliding glass door.
- Press the control bar briefly; the display changes to zero.

Note: It is possible to carry out external taring by using the handkey or foot pedal from the "accessories, optional" (connection sockets on rear of balance).

The weight of the container is now tared out. To weigh-in, the balance weighing range - minus the weight of the tare container - is now available.

display goes out.

The result is then stable.

Note: When the green dot lights up in the display, the data interface is blocked; when the green dot goes out (stability), the data interface is unblocked.

DeltaRange:



Your AE260 has a coarse range from 0...205 g; in this range, readability is 1 mg. The DeltaRange (fine range) turns your "milligram balance" into an "analytical balance". This means that the readability is increased to 0.1 mg in a range of 60 g (by pressing tare each time, it can be moved throughout the entire weighing range). Every time the fine range is exceeded, the last decimal goes out; you are then weighing in the coarse range.

Specifications

| | | |
|---|--|---|
| Readability | 0.1 mg | 1 mg |
| Weighing range | 0...60 g | 0...205 g |
| Tare range (subtractive) | 0...60 g | 0...205 g |
| Reproducibility (standard deviation) | 0.1 mg | 0.5 mg |
| Linearity | ±0.2 mg | ±1 mg |
| Stabilization time (typically) | 5 sec | |
| Integration time (adjustable) | 1.5/3/6 sec | |
| Display sequence | - Mettler DeltaDisplay off - Mettler DeltaDisplay on | 0.4 sec 0.2/0.4 sec |
| Stability detector | - Sensitivity selectable in three steps | 1/2/off |
| Sensitivity drift (10...30°C) | | |
| Calibration weight (built-in), adjusted to an apparent mass of 8.0 g/cm³ in air at density of 1200 mg/l | | 100 g; adjusted to ±0.1 mg |
| Dimensions: | Weighing pan (stainless steel) Open space above weighing pan Balance housing (W x D x H) Net weight | 80 mm dia. 215 mm 205 x 410 x 290 mm 10.3 kg |
| Power supply: | Voltage, adjustable Admissible voltage range Frequency Power consumption | 115 V/220 V 92...132 V, 184...265 V 50...60 Hz 10 VA |
| Admissible ambient conditions during operation: | Temperature Relative humidity (non-condensing) | 10...40°C 25...85% |

What's wrong if...

... the entire display does not light up?

... the OFF display appears?

... only the upper horizontal segments light up in the display?

only the lower horizontal segments light up in the display?

the weighing result is unstable?

the weighing result is obviously incorrect?

only a portion of the display lights up?

the middle horizontal segments in the display are blinking (for more than 30 sec)?

CAL Err appears in the display?

no CAL appears in the display?

a zero display does not appear after pressing tare?

- Place the fuse holder back in.
- Plug the power-line cable back in.

Accessories

Optional equipment

| Optional equipment | Order No. |
|--|-----------|
| - Windshield ring, can be stacked: 1 unit | 38594 |
| - Tweezers, 210 mm long (with plastic tips) | 70209 |
| - Density (specific gravity) determination kit | 33340 |
| - Foot pedal | 46278 |
| - Handkey | 42500 |
| - Microfuses, 160 mA slow-blowing (set of 3) | 55144 |
| - Data interfaces: | |
| 011 Option - CL/RS232C unidirectional | 38750 |
| 012 Option - CL/RS232C bidirectional | 38751 |
| 013 Option - IEEE488 | 38752 |
| 040 Data Output (unidirectional mode) | 38795 |

Standard equipment

| | | |
|--|--|----------------------------------|
| - Power-line cable | neutral Switzerland Germany USA | 87576 87920 87925 88668 |
| - Weighing pan, 80 mm dia. | | 38590 |
| - Centering disk (for windshield ring) | | 38609 |
| - Hair-bristle brush | | 70114 |
| - Windshield ring | | 38689 |

AE 260 DeltaRange

| | |
|----------------------------|-----------|
| 60 g DeltaRange | 200 g |
| 0.1 mg | 1 mg |
| 0...60 g | 0...205 g |
| 0...60 g | 0...205 g |
| 0.1 mg | 0.5 mg |
| ±0.2 mg | ±1 mg |
| 5 sec | |
| 1.5/3/6 sec | |
| 0.4 sec | |
| 0.2/0.4 sec | |
| 1/2/off | |
| 100 g; adjusted to ±0.1 mg | |
| 80 mm dia. | |
| 215 mm | |
| 205 x 410 x 290 mm | |
| 10.3 kg | |
| 115 V/220 V | |
| 92...132 V, 184...265 V | |
| 50...60 Hz | |
| 10 VA | |

then...

- no power reaching the instrument.
- the fuse is defective.
- a temporary power failure has taken place. (Press the control bar.)
- the weighing range has been exceeded.
- the calibration weight has been activated.
- there was weight on the pan when the instrument was switched on.
- the weighing pan is not installed.
- there was weight on the pan when the instrument was switched on.
- there are too many drafts.
- the weighing table is unstable.
- the integration time setting is too low.
- the object being weighed is not at room temperature.
- the balance must be calibrated or has been calibrated using the wrong external weight.
- a temporary malfunction has occurred (pull out power cable and plug it back in).
- the weighing table or the load is too unsteady (close sliding glass doors, set a longer integration time and/or change the stability detection setting).
- the weighing pan was not unloaded before calibrating the balance, or the wrong external calibration weight was used (return to the weighing mode by pressing and holding the control bar).
- a temporary malfunction has occurred (recalibrate balance).
- the weighing table or the load is too unsteady (close sliding glass doors, set a longer integration time and/or change the stability detection setting).